

Purchasing Summary

EVENT # 7952	TITLE: Biosolid Dryer Repair Parts	COST: \$130,000
TYPE OF PROCUREMENT: Sole Source	ANNUAL CONTRACT <input type="checkbox"/> ANNUAL MAINTENANCE AGREEMENT <input type="checkbox"/>	ONE TIME PURCHASE <input checked="" type="checkbox"/>
CONTRACT TERM (IF APPLICABLE) N/A		
S/DBE (IF APPLICABLE) N/A		
MATRIX (IF APPLICABLE) N/A		

NOTES

Recommend approval to procure repair parts for a biosolid (sludge) dryer from Huber Technology in the amount of \$130,000. Water Reclamation Staff will use new Original Equipment Manufacturer (OEM) parts to repair the sludge dryer located at the President Street Plant.

The dryer system experienced a small fire in which some of the internal components were damaged and need repair.

This is a sole source because the new OEM parts from Huber Technology must be used to maintain the warranty.

S.S. Huber Technology (Huntersville, NC)^(D) \$130,000

(D) Indicates non-local, non-DBE business. Recommend approval.

Local available: No

Total sent: 1

Total received: 1